



Transportation
Safety Board
of Canada

Bureau de la sécurité
des transports
du Canada



RAIL TRANSPORTATION SAFETY INVESTIGATION REPORT R25T0177

CROSSING COLLISION

Canadian Pacific Railway Company, doing business as CPKC
Intermodal train 113-13
Mile 115.64, CPKC Belleville Subdivision
Township of Cramahe, Ontario
14 July 2025

The Transportation Safety Board of Canada (TSB) investigated this occurrence for the purpose of advancing transportation safety. It is not the function of the Board to assign fault or determine civil or criminal liability. **This report is not created for use in the context of legal, disciplinary or other proceedings.** See the Terms of use at the end of the report. Masculine pronouns and position titles may be used to signify all genders to comply with the *Canadian Transportation Accident Investigation and Safety Board Act* (S.C. 1989, c. 3).


The occurrence

On 14 July 2025, at about 0809,¹ intermodal freight train 113-13 of the Canadian Pacific Railway Company, doing business as CPKC, was proceeding westward at 56 mph on the CPKC Belleville Subdivision when it collided with a southbound pickup truck (the vehicle) as it was traversing the Hunt Road grade crossing (Mile 115.64) in Cramahe, a rural township in southern Ontario² (Figure 1). On impact, the vehicle was thrown to the southwest. The vehicle driver, and sole occupant, was fatally injured.

¹ All times are Eastern Daylight Time.

² All locations are in the province of Ontario.

Figure 1. Main image showing the occurrence location in relation to Toronto, and inset image showing an aerial view of the grade crossing where the occurrence took place (Source of main image: Railway Association of Canada, Canadian Rail Atlas, with TSB annotations; source of inset image: Google Maps, with TSB annotations)



Crossing information

In the area of the occurrence, there are 2 railway crossings within 200 m of each other. One traverses the double main track of the Canadian National Railway Company (CN) Kingston Subdivision; the other traverses the single main track of the CPKC Belleville Subdivision. A southbound vehicle on Hunt Road crosses the CN tracks on the approach to the CPKC railway crossing.

The CN crossing is an automated public crossing. It is equipped with an active train warning system (flashing lights, a bell, and gates) that activates when a train is approaching or occupying the crossing. Road users are warned of an approaching train before the train is visible.

The CPKC crossing further south (the occurrence crossing) is a passive public crossing equipped with a standard retroreflective crossing sign (SRCS) and a stop sign. In the final approach to the crossing from the southbound direction, the road curves gently to the left, on a 5° downgrade, and crosses the Belleville Subdivision at an 85° angle (figures 2 and 3). The surface of the public roadway is paved and, at the time of the occurrence, the pavement was dry.

Crossing protection (automated or passive) at any given crossing is dependent on factors such as rail and road traffic volumes and maximum speed of both trains and vehicles.

Figure 2. Southbound approach to the CPKC Hunt Road grade crossing (Source: TSB; photo taken on 16 July 2025 in environmental conditions similar to the conditions at the time of the occurrence)



Figure 3. View to the southeast of the CPKC Hunt Road grade crossing, from a position approximating that of a driver of a southbound vehicle (Source: TSB; photo taken on 16 July 2025 in environmental conditions similar to the conditions at the time of the occurrence)



Train activity data suggest that normally 2 to 3 trains per day pass the CPKC Hunt Road crossing during daylight.³

The vehicle driver in this occurrence routinely traversed the 2 crossings and was familiar with them.

Passive public grade crossings

Passive public grade crossings rely on road signs to notify drivers of an upcoming railway crossing. All passive public crossings include at a minimum an SRCS, which can be supplemented with a stop sign.

Passive public crossing systems do not warn drivers of an approaching train; they rely on the vehicle driver to take the necessary steps to avoid a collision.

At passive public crossings equipped with only an SRCS, vehicles are not required to stop but must be prepared to yield to any approaching train. At crossings equipped with both an SRCS and a stop sign, vehicles are required to stop, whether or not a train is present.

In 2024, there were approximately 12 500 public grade crossings on federally regulated rail lines in Canada. Of these, about 7000 had passive protection (69% were equipped with an SRCS only, the other 31% featured an SRCS supplemented with a stop sign). Between 2015 and 2024, the

³ Data provided by RailState, from its Rail Network Intelligence database.

number of passive grade crossings equipped with an SRCS supplemented with a stop sign has more than doubled.⁴

Recorded information

As part of the investigation, data from the vehicle's event data recorder for the 2.5 seconds⁵ before the collision were reviewed by the TSB laboratory in Ottawa.

The data indicate that the vehicle was travelling at about 26 km/h while approaching the crossing, below the 80 km/h speed limit. Upon seeing the train, the driver attempted to accelerate clear of the crossing, with a possible moment of hesitation.

The data from the vehicle and from the locomotive event recorder on the train were also used by the TSB laboratory to conduct a photogrammetric analysis based on distances, velocity, and acceleration to determine if there was enough time, once the driver perceived the approaching train, to stop the vehicle and avoid the collision. The results indicate that the vehicle's speed of travel was too great to have permitted the driver to stop the vehicle short of the crossing based on the vehicle's position once the train became visible to the driver (approximately 2.2 seconds before the collision). Furthermore, the results are not consistent with a vehicle preparing to stop short of the crossing.

The TSB laboratory also inspected the vehicle right-side brake system and wheel assemblies. It determined that there were no visible faults, other than those resulting from the collision.

Sightlines

Under the *Grade Crossings Regulations*, the responsibility of maintaining sightlines at all public crossings is shared by the railway and the road authority. At public passive crossings equipped with both an SRCS and a stop sign, sightlines ensure that approaching trains are visible from a vehicle in a stopped position.

The day after the occurrence, Transport Canada (TC) inspected the crossing and found non-compliances with the *Grade Crossings Regulations*. The TC inspection expressed concern about the sightlines from the stopping sight distance, indicating that they "may not be adequate for the grades as well as current road use."⁶ Furthermore, TC indicated that "vegetation management [was] required along all approaches of the crossing to ensure that all warning signs are visible to road users."

⁴ Data reported under section 12.3(g) of the *Transportation Information Regulations* (SOR/96-334), which require that Class I, II and III rail carriers annually report the location of, and type of warning system for, each grade crossing. The number of crossings with both a standard reflectorized crossing sign and a stop sign has increased from 2115 in 2015 to 5431 in 2024, an increase of 3316 (2.6x).

⁵ Only 2.5 seconds of data from the vehicle's event data recorder were available.

⁶ Transport Canada, Transport Canada Rail Safety – Crossings Inspection Report, Township of Cramahe (15 July 2025).

For a vehicle driver unfamiliar with a crossing, warning sign visibility could affect the driver's ability to recognize and comply with the requirement to stop. However, in this occurrence, the vehicle driver was familiar with the crossing and therefore likely aware of the requirement to stop.

Train horn audibility

The effectiveness of train horns is affected by horn location, the speed of the train, and the dampening of sound through the road-vehicle shell.⁷ In this occurrence, the train horn was sounded in compliance with the *Canadian Rail Operating Rules* and continued when it became apparent that the vehicle was not stopping.

The driver's car windows were closed and the engine was running at the time of the collision. Previous investigations have demonstrated that train horns may not be audible to a vehicle driver under such circumstances until the train is less than 2 seconds from the point of collision.⁸ The vehicle driver's behaviour was consistent with him not hearing the train before it became visible.

Research on driver compliance at stop signs

The required vehicle driver behaviour at a stop sign is to bring the vehicle to a complete stop, look in all directions for traffic, and then proceed when the driver deems it safe to do so. The defence against a collision at a passive grade crossing equipped with a stop sign relies on driver compliance. If the vehicle driver does not stop, as often happens, the system fails. There is considerable evidence showing that what happens in practice differs from what is required. A study on driver behaviour at a road T-intersection controlled by stop signs showed that only 4.6% of vehicle drivers performed a legal stop when there was no oncoming traffic.⁹ In contrast, 100% of vehicle drivers in this research performed a legal stop when oncoming traffic was present.

A similar pattern of vehicle driver behaviour has been observed at passive railway grade crossings equipped with a stop sign. A study conducted at one crossing reported that stopping compliance ranged from 61% to as low as 29% for a familiar crossing.¹⁰ A study by the U.S. National Transportation Safety Board cited another study¹¹ in which only 18% of vehicle drivers came to a complete stop, even when there was no available sightline.

⁷ G. W. English and T. N. Moore, *Locomotive Horn Evaluation: Effectiveness at Operating Speeds*, TP 14103E, TranSys Research Ltd. (on behalf of Transport Canada), 2003.

⁸ TSB rail transportation safety investigation reports R18T0006, R13E0015, R13D0001, R10W0123, R11T0175, R08M0002, R04H0014, and R02W0063.

⁹ A. R. Lebbon, J. Austin, R. Van Houten, and L. E. Malenfant, "Evaluating the effects of traffic on driver stopping and turn signal use at a stop sign: A systematic replication," *Journal of Organizational Behavior Management*, 27(2) (2007), pp. 27-35.

¹⁰ P. S. Parsonson and E. J. Rinalducci, "Positive-guidance demonstration project at a railroad-highway grade crossing," in *Automotive Technology, Information Needs of Highway Users, and Promotion of Safety Belt Usage*, *Transportation Research Record 844*, Washington, DC: Transportation Research Board, National Research Council (1982), pp. 29-34.

¹¹ A. Burnham, "Stop sign effectiveness at railroad grade crossings (abuse without excuse)," in *Proceedings: Third International Symposium on Railroad-Highway Grade Crossing Research and Safety* (Knoxville, TN: University of Tennessee, 1995), pp. 91-113, cited in National Transportation Safety Board, *Safety Study: Safety*

The research asserts that a vehicle driver behaviour at a stop sign is context-dependent and changes based on a driver's perceived risk of collision with oncoming traffic. If the perceived risk of a collision is low because the driver does not currently observe other traffic and/or knows that traffic is infrequent, the normative behaviour of a vehicle driver will be to not come to a complete stop.

Driver compliance based on perceived likelihood of collision

Although a decision maker tends to overestimate the likelihood of a rare event in the abstract, research has shown that, in practice, they make decisions that underestimate the likelihood of the rare event.¹² When the decision maker's mental model is primarily informed by experience with a given task or scenario (compared to a mental model being informed by theory), the decision maker tends to underestimate the likelihood of rare events. One explanation for this underestimation is that the decision maker tends to rely on limited experiences, most notably those associated with recent similar experiences.

In this occurrence, given his familiarity with the crossing, the vehicle driver would have observed that trains did not travel along that track very frequently. Therefore, a scenario where a train arrived at the same time as his vehicle was occupying the crossing likely would have been perceived as an extremely rare event. Even rarer still would have been a scenario where a collision occurs. The perceived extreme unlikelihood of these scenarios would have been reinforced by the fact that the crossing where the collision occurred had less protection than the crossing immediately to the north, which had higher activity.

This type of driver decision making—and the resulting behaviour—is not unique to this occurrence. A recent report by the Australian Transport Safety Bureau found that, in 12 of 24 collisions at grade crossings between 2014 and 2022, the vehicle driver used the occurrence crossing on a regular basis. The report attributed this finding to previous experience with the occurrence crossing, leading to a low expectancy for trains, and therefore to an underestimation of the risk of not coming to a complete stop.¹³

Other train–vehicle collision at the CPKC Hunt Road crossing

According to TSB data, over the past 20 years, there was one other crossing accident at the CPKC Hunt Road crossing. On 18 October 2022, at about 1800, a northbound pickup truck pulling a trailer slid to a stop on the crossing and was struck by westbound CPKC train 231-18 travelling at 52 mph.¹⁴ The driver, who was familiar with the crossing, had been proceeding in the dark on a drizzly foggy evening at an estimated speed of 35 km/h, scanning for an approaching train as the

at Passive Crossings, Volume 1: Analysis, NTSB/SS-98/02, PB98-917004, Notation 7036 (adopted 21 July 1998).

¹² G. Barron and E. Yechiam, "The coexistence of overestimation and underweighting of rare events and the contingent recency effect," *Judgment and Decision Making*, 4(6) (October 2009), pp. 447-460.

¹³ Australian Transport Safety Bureau, *Review of level crossing collisions involving trains and heavy road vehicles in Australia*, Safety study RS-2021-001 (March 2024).

¹⁴ TSB Rail Transportation Occurrence R22T0197.

vehicle cleared the treeline.¹⁵ The vehicle driver saw the headlight of an approaching train and immediately applied the brakes. The pickup came to rest on the tracks just as the train arrived.

TSB laboratory reports

The TSB completed the following laboratory reports in support of this investigation:

- LP063/2025 – Vehicle Performance Analysis

Safety action taken

On 15 July 2025, CPKC performed localized brush cutting activities to improve sightlines in the vicinity of Mile 115.64 of the Belleville Subdivision. The railway also cleared brush partially obstructing northward and southward advance warning signs for this crossing.

On 24 July 2025, following its 15 July inspection of the crossing at Hunt Road crossing, TC issued a Letter of Non-Compliance to the Township of Cramahe describing the non-compliances and concern noted at the crossing. The non-compliances were related to signage and crossing surface conditions, and a concern was also noted for sightlines at the crossing. TC conducted a follow-up inspection on 24 August 2025 during which it identified that no visible change in the conditions noted in the Letter of Non-Compliance had taken place. Therefore, TC sent a Letter of Insufficient Action to the Township of Cramahe highlighting the items that required its further attention. On 12 September 2025, the Township of Cramahe indicated to TC that the vegetation had been cleared. On 16 October 2025, the Township finished the pavement markings at the crossing.

Safety message

It is important that railways—in conjunction with road authorities, regulators responsible for grade crossing safety, and other stakeholders—assess whether the defence built on the requirement to stop at a passive crossing equipped with a stop sign can be supplemented to improve rail crossing safety.

This report concludes the Transportation Safety Board of Canada's investigation into this occurrence. The Board authorized the release of this report on 25 February 2026. It was officially released on 04 March 2026.

Visit the Transportation Safety Board of Canada's website (www.tsb.gc.ca) for information about the TSB and its products and services. You will also find the Watchlist, which identifies the key safety issues that need to be addressed to make Canada's transportation system even safer. In each case, the TSB has found that actions taken to date are inadequate, and that industry and regulators need to take additional concrete measures to eliminate the risks.

¹⁵ The distance between the edge of the trees and the track for northbound vehicles was about twice the distance for southbound vehicles.

ABOUT THIS INVESTIGATION REPORT

This report is the result of an investigation into a class 4 occurrence. For more information, see the Policy on Occurrence Classification at www.tsb.gc.ca

The Transportation Safety Board of Canada (TSB) investigated this occurrence for the purpose of advancing transportation safety. It is not the function of the Board to assign fault or determine civil or criminal liability.

TERMS OF USE

Use in legal, disciplinary or other proceedings

The *Canadian Transportation Accident Investigation and Safety Board Act* states the following:

- 7(3) No finding of the Board shall be construed as assigning fault or determining civil or criminal liability.
- 7(4) The findings of the Board are not binding on the parties to any legal, disciplinary or other proceedings.

Therefore, the TSB's investigations and the resulting reports are not created for use in the context of legal, disciplinary or other proceedings.

Notify the TSB in writing if this investigation report is being used or might be used in such proceedings.

Non-commercial reproduction

Unless otherwise specified, you may reproduce this investigation report in whole or in part for non-commercial purposes, and in any format, without charge or further permission, provided you do the following:

- Exercise due diligence in ensuring the accuracy of the materials reproduced.
- Indicate the complete title of the materials reproduced and name the Transportation Safety Board of Canada as the author.
- Indicate that the reproduction is a copy of the version available at [URL where original document is available].

Commercial reproduction

Unless otherwise specified, you may not reproduce this investigation report, in whole or in part, for the purposes of commercial redistribution without prior written permission from the TSB.

Materials under the copyright of another party

Some of the content in this investigation report (notably images on which a source other than the TSB is named) is subject to the copyright of another party and is protected under the *Copyright Act* and international agreements. For information concerning copyright ownership and restrictions, please contact the TSB.

Citation

Transportation Safety Board of Canada, *Rail Transportation Safety Investigation Report R25T0177* (released 04 March 2026).

Transportation Safety Board of Canada
200 Promenade du Portage, 4th floor
Gatineau QC K1A 1K8
819-994-3741; 1-800-387-3557
www.tsb.gc.ca
communications@tsb.gc.ca

© His Majesty the King in Right of Canada, as represented by the Transportation Safety Board of Canada, 2026

Rail transportation safety investigation report R25T0177

Cat. No. TU3-11/25-0177E-PDF

ISBN 978-0-660-98318-9

This report is available on the website of the Transportation Safety Board of Canada at www.tsb.gc.ca

Le présent rapport est également disponible en français.